Sumner Village Lateral Defect Map Legend

- Manhole
- 1. Excellent: Failure unlikely in foreseeable future.
- 2. Good: has not begun to deteriorate.

. Moderately poor: moderate defects that will continue to deteriorate.

7. Unknown defects.

- 4. Very poor: pipe will become 5 in the near future.
- 5. Material failure: pipe requires immediate attention.
- 6. Pipe is lined.

